

TAMPS 6.1/6.1.1



Jim Lacey
PMA-2336.1/BAI
19 May 1998
(301) 757-8011




OAG Impact on 6.1/6.1.1

- Top 2 priorities from May 97 OAG
 - Increased reliability, stability and performance
 - HMI/Mission planning functionality
- 6.1/6.1.1 improvements
 - Addressed software reliability and stability
 - Corrected 32 STRs causing crashes
 - Increased performance
 - Introduced new hardware in 6.1.1
 - Corrected HMI deficiencies defined by FUIWG
 - Delayed 6.1 for 3 months to fix
 - Incorporated new functionality for mission planning
 - GPS data load
 - Improved weapons planning



FUIWG HMI Enhancements

- Reorganized MPM Menu
 - Allowed easier access to menus for mission planning
- Enhanced User Defined Menu
 - Each platform could establish default menu
- Changed software to meet FUIWG defined HMI stds
 - HMI became more consistent throughout system
- Saved OPAREA and MU files with mission
 - Changed for all aircraft MPMs





FUIWG HMI Enhancements (cont.)

- F/A-18 MPM improved interface with MU and MU waypoints
 - Simplified loading of MU by planner
- Set Autosave Default to ON
 - Eliminated major headache for planners
- Changed Edit Flight Parameters
 - Simplified menu for easier use
- Modified terminology in menus
 - Changed from engineering terms to aviator




6.1/6.1.1 Functionality

- 6.1 introduced
 - GPS MDL planning and loading
 - Loading of MIDS to support F/A-18
 - ARC-210 planning and loading
 - Coordination of weapon and aircraft routes
 - Improved printed reports for helos
 - Last minute threat updates
 - TERPES applications
 - Platform unique symbology
 - Tactical waypoint definition
 - COMPASS
- 6.1.1 hosted 6.1 on Ultra 2 hardware
 - Supports E-2C and F-14 aircraft
 - GPS MDL load for E-2C Nav Upgrade aircraft



Hardware Overview

- ACE and DTC-2 hardware will be cycled out of the fleet after 6.2 fleet release
- Ultra hardware will be used for 6.1.1 and 6.2





6.1.1 Hardware

Sun Ultra 2 Model consisting of:

- » Single Processor
- » 256 MB RAM
- » 18 GB Disk Capacity
- » CD-ROM
- » 3.5" Floppy
- » 8mm Tape Drive
- » ATM Network Card
- » Creator 24 Bit Graphics, with 20" Color Monitor
- » Xerox C55MP Color/BW Printer
- » Appropriate Data Load Devices




9 Bay SCSI Enclosure not available for photo



6.1/6.1.1 OT Status

- CVW-9 and CVW-1 received 6.1 training at NSAWC
 - VX-9 collected data for OT Report
- Quick Look Message was requested from OPTEVFOR in Aug 97 to support CV deployments
 - 6.1 was determined to be great improvement over 6.0.3
- Final test report completed Feb 98





6.1/6.1.1 OT Report Card

6.1/6.1.1 Goals	Success	Results
A. Provide new or improved mission planning functionality	G G G G G G G G G R R R R R R	A. Operationally effective for <ol style="list-style-type: none"> 1. GPS data load support. 2. F/A-18 SCS 11C and 91C and data load 3. SLAM weapon planning and data load 4. HARM data load 5. JSOW weapon planning and data load 6. F-14 tactical waypoint data load 7. E-2C mission data load 8. JTIDS initialization file data loads (E-2C and F-14) 9. FAMP B. Not operationally effective for <ol style="list-style-type: none"> 1. ARC-210 initialization 2. RTM generation 3. Strike planning 4. Cockpit quality outputs 5. Environmental effects analysis 6. Joint interoperability
B. Improve system reliability	G G G G	A. Improved software reliability (>30 hrs in ORD) <ol style="list-style-type: none"> 1. 44 hrs for ACE (6.1) 2. 60 hrs for DTC-2 (6.1) 3. 129 hrs for Ultra 1200 (6.1.1)
C. Improve hardware	G G G G	A. Improved speed in Ultra 1200 B. Xerox C55 printer (6.1.1) produced cockpit quality charts C. Increased data storage for DTC-2 and Ultra
D. Improve HMI	G G	A. Improved HMI for F/A-18 MPM B. Improved HMI for generic route planning



Summary

- 6.1/6.1.1 addressed OAG top priorities
 - Improved HMI for planners
 - Provided GPS data load capabilities
 - Provided fast and reliable hardware
 - Improved reliability and stability of software
- Future software deliveries will address deficiencies noted by OAG and OT Report

